


25 METER ZEROING TARGET - M4 CARBINE



- 1- FOR ZEROING AT 25 METERS, ROTATE THE REAR SIGHT ELEVATION KNOB TO THE 300 METER (6/3) SETTING. (DO NOT USE THE "Z" MARK ON THE ELEVATION KNOB.)
- 2- AIM AT THE TARGET CENTER. ADJUST SIGHTS TO MOVE SHOT GROUP CENTER AS CLOSE AS POSSIBLE TO THE WHITE DOT IN THE CENTER OF THE TARGET.
- 3- AFTER COMPLETING THE 25 METER ZERO, THE WEAPON WILL BE ZEROED FOR 300 METERS.